


PPAP & IATF 16949 FLOW: FROM DESIGN REVIEW TO MASS PRODUCTION



⟳ Continuous Improvement: Ongoing feedback loop between DFMEA ↔ PFMEA ↔ Control Plan for zero-defect production.

✉ Need a complete PPAP checklist? Email: info@obd-cable.com